


DIN 138  $\lambda=10^\circ$   $\gamma=10^\circ$  typ H

HSSE = litá HSS  
 cast HSS  
 HHS fondu  
 литая HSS



Použití / Usage / Domaines d'application / Употребление

1 2 3 4 5 6 7 8 9 10 11 12 13

D js 16	S e 8	d H 7	Z	CODE
50	4	16	18	732373.05004
63	5	22	20	732373.06305
63	6	22	20	732373.06306
63	8	22	20	732373.06308
80	10	27	22	732373.08010
80	12	27	22	732373.08012
80	14	27	22	732373.08014
100	16	32	24	732373.10016
100	18	32	24	732373.10018
125	22	40	26	732373.12522
125	25	40	26	732373.12525